

Fire Suppression Supplemental Form

Location Code: YYJDOVX

Contact: Owner or Manager

Contact Address: 112 ORION STREET
Brunswick, ME 04011

Phone:

Email:

Property Evaluated: MRRA - HANGAR 5 (Assembly)
112 ORION STREET
Brunswick, ME 04011

Description: Fire Suppression Supplement (Foam Suppression System)

Work Order: SV2307030270/1

Company: Eastern Fire

Address: 170 Kittyhawk Ave., P.O. Box 1390
Auburn, ME 04210

Company Phone: 207-784-1507

Company Fax: 207-782-0566

Inspector: Alex Haggan
Not Required

Date of Work: 7/6/2023

Deficiency Summary

Status: Open

Deficiency for Device Type: FLAME DETECTOR, Address: M101, Location: BAY 1 FLAME DETECTOR.

Covered

Status: Open

Deficiency for Device Type: FLAME DETECTOR, Address: M102, Location: BAY 1 FLAME DETECTOR.

Covered

Status: Open

Deficiency for Device Type: FLAME DETECTOR, Address: M103, Location: BAY 1 FLAME DETECTOR.

Covered

Status: Open

Deficiency for Device Type: FLAME DETECTOR, Address: M104, Location: BAY 2 FLAME DETECTOR.

Covered

Status: Open

Deficiency for Device Type: FLAME DETECTOR, Address: M105, Location: BAY 2 FLAME DETECTOR.

Covered

Status: Open

Deficiency for Device Type: FLAME DETECTOR, Address: M106, Location: BAY 3 FLAME DETECTOR.

Covered

Status: Open

Deficiency for Device Type: FLAME DETECTOR, Address: M107, Location: BAY 3 FLAME DETECTOR.

Covered

Status: Open

Deficiency for Device Type: FLAME DETECTOR, Address: M108, Location: BAY 3 FLAME DETECTOR.

Covered

Status: Open

Deficiency for Device Type: FLAME DETECTOR, Address: M109, Location: BAY 7 FLAME DETECTOR.

Covered

Status: Open

Deficiency for Device Type: FLAME DETECTOR, Address: M110, Location: BAY 7 FLAME DETECTOR.

Covered

Status: Open

Deficiency for Device Type: FLAME DETECTOR, Address: M111, Location: BAY 7 FLAME DETECTOR.

Covered

Status: Open

Deficiency for Device Type: FLAME DETECTOR, Address: M112, Location: BAY 7 FLAME DETECTOR.

Covered

Status: Open

Deficiency for Device Type: FLAME DETECTOR, Address: M201, Location: BAY 4 FLAME DETECTOR.

Covered

Status: Open

Deficiency for Device Type: FLAME DETECTOR, Address: M202, Location: BAY 4 FLAME DETECTOR.

Covered

Status: Open

Deficiency for Device Type: FLAME DETECTOR, Address: M203, Location: BAY 4 FLAME DETECTOR.

Covered

Status: Open

Deficiency for Device Type: FLAME DETECTOR, Address: M204, Location: BAY 5 FLAME DETECTOR.

Covered

Status: Open

Deficiency for Device Type: FLAME DETECTOR, Address: M205, Location: BAY 5 FLAME DETECTOR.

Covered

Status: Open

Deficiency for Device Type: FLAME DETECTOR, Address: M206, Location: BAY 6 FLAME DETECTOR.

Covered

Status: Open

Deficiency for Device Type: FLAME DETECTOR, Address: M207, Location: BAY 6 FLAME DETECTOR.

Covered

Status: Open

Deficiency for Device Type: FLAME DETECTOR, Address: M208, Location: BAY 6 FLAME DETECTOR.

Covered

General Comments

These items are outside the regular scope of the required inspection and are not the result of an engineering review. This information is not intended to be all-inclusive but rather a list of items discovered as a by-product of the required inspection.

There are no general comments for this submission



Eastern Fire
170 Kittyhawk Ave., P.O. Box 1390
Auburn, ME 04210
Phone: 207-784-1507

Fire Suppression Supplemental Form

The work covered on this form is (select one):

Date of Work

Annual

7/6/2023

Account Information				
Facility Name: MRRA - HANGAR 5	Property Type: Assembly	Location Code: YYJDOVX		
Service Address: 112 ORION STREET, Brunswick, ME, 04011				
Owner: Owner or Manager	Owner's Phone:			
Owner's Address: 112 ORION STREET, Brunswick, ME, 04011				

Legend					
AS - Abort Station	BATT - Batteries	CoD - Carbon Monoxide Detector	CM - Control Module	DA - Damper	
DD - Duct Detector	DH - Door Holder	EL - Emergency/Exit Light	HD - Heat Detector	HORN - Horns	H/S - Horn-Strobes
LA - Low Air	MM - Monitor Module (Ansul, temp, CO, etc)	MR - Manual Release	Other	PR - Phase Reversal	
PS - Pull Station	PWS - Power Supply	SC - Signal/Sounder Control	SD - Smoke Detector	SD-Ion - Ion Smoke Detector	
SD-Photo - Photo Smoke Detector	SPKR - Speakers	STROBE - Strobes	TS - Tamper Switch	WF - Waterflow	

Type	Total	Tested	Not Tested	Passed	Failed
FLAME DETECTOR	20	20	0	0	20
RELEASING HEAD	7	7	0	7	0

Type	Total	Tested	Not Tested	Passed	Failed
MM	2	2	0	2	0

Zone: LOOP 1 INITIATING

Zone: LOOP 1 INITIATING						
Type	Address	Location	Notes	Last Tested	Test Results	Comments
FLAME DETECTOR	M101	BAY 1 FLAME DETECTOR		7/6/2023	Fail	Covered
FLAME DETECTOR	M102	BAY 1 FLAME DETECTOR		7/6/2023	Fail	Covered
FLAME DETECTOR	M103	BAY 1 FLAME DETECTOR		7/6/2023	Fail	Covered



Eastern Fire
170 Kittyhawk Ave., P.O. Box 1390
Auburn, ME 04210
Phone: 207-784-1507

Zone: LOOP 1 INITIATING						
Type	Address	Location	Notes	Last Tested	Test Results	Comments
■ RELEASING HEAD	M120	BAY 1 FOAM SOLENOID		7/6/2023	Pass	
■ FLAME DETECTOR	M104	BAY 2 FLAME DETECTOR		7/6/2023	Fail	Covered
■ FLAME DETECTOR	M105	BAY 2 FLAME DETECTOR		7/6/2023	Fail	Covered
■ RELEASING HEAD	M121	BAY 2 FOAM SOLENOID		7/6/2023	Pass	
■ FLAME DETECTOR	M106	BAY 3 FLAME DETECTOR		7/6/2023	Fail	Covered
■ FLAME DETECTOR	M107	BAY 3 FLAME DETECTOR		7/6/2023	Fail	Covered
■ FLAME DETECTOR	M108	BAY 3 FLAME DETECTOR		7/6/2023	Fail	Covered
■ RELEASING HEAD	M122	BAY 3 FOAM SOLENOID		7/6/2023	Pass	
■ FLAME DETECTOR	M109	BAY 7 FLAME DETECTOR		7/6/2023	Fail	Covered
■ FLAME DETECTOR	M110	BAY 7 FLAME DETECTOR		7/6/2023	Fail	Covered
■ FLAME DETECTOR	M111	BAY 7 FLAME DETECTOR		7/6/2023	Fail	Covered
■ FLAME DETECTOR	M112	BAY 7 FLAME DETECTOR		7/6/2023	Fail	Covered
■ RELEASING HEAD	M123	BAY 7 FOAM SOLENOID		7/6/2023	Pass	
■ MM	M124	POWER MONITOR FLAME DETECTORS BAYS 1/2/3/7		7/6/2023	Pass	

Zone: LOOP 2 INITIATING

Zone: LOOP 2 INITIATING						
Type	Address	Location	Notes	Last Tested	Test Results	Comments
■ FLAME DETECTOR	M201	BAY 4 FLAME DETECTOR		7/6/2023	Fail	Covered
■ FLAME DETECTOR	M202	BAY 4 FLAME DETECTOR		7/6/2023	Fail	Covered
■ FLAME DETECTOR	M203	BAY 4 FLAME DETECTOR		7/6/2023	Fail	Covered



Eastern Fire
170 Kittyhawk Ave., P.O. Box 1390
Auburn, ME 04210
Phone: 207-784-1507

Zone: LOOP 2 INITIATING						
Type	Address	Location	Notes	Last Tested	Test Results	Comments
■ RELEASING HEAD	M221	BAY 4 FOAM RELEASE		7/6/2023	Pass	
■ FLAME DETECTOR	M204	BAY 5 FLAME DETECTOR		7/6/2023	Fail	Covered
■ FLAME DETECTOR	M205	BAY 5 FLAME DETECTOR		7/6/2023	Fail	Covered
■ RELEASING HEAD	M222	BAY 5 FOAM RELEASE		7/6/2023	Pass	
■ FLAME DETECTOR	M206	BAY 6 FLAME DETECTOR		7/6/2023	Fail	Covered
■ FLAME DETECTOR	M207	BAY 6 FLAME DETECTOR		7/6/2023	Fail	Covered
■ FLAME DETECTOR	M208	BAY 6 FLAME DETECTOR		7/6/2023	Fail	Covered
■ RELEASING HEAD	M223	BAY 6 FOAM RELEASE		7/6/2023	Pass	
✉ MM	M224	POWER MONITOR FLAME DETECTORS BAYS 4/5/6		7/6/2023	Pass	

Comments

Any deficiencies or other problems found with the devices must be explained using the comment specific for each device. Additional comments can be added here.

Please see the summary section at the top of the form for the comments.

Inspector's Information

Inspected By

Alex Hagan

Inspector License:

Not Required

I state that the information on this form is correct at the time and place of my inspection, and that all equipment tested at this time was left in operating condition upon completion of this inspection except as noted in the *Comments*.

Signature of Inspector

Date

7/6/2023